



Customer and Market Operations  
007/09.03.09  
EMEA Customer Care

Service Bulletin No. SB-

RH-30

## SPARE PARTS LIST AND SWAP PACKAGES (LEVEL 2)

Version history:		
Version 22	09.03.09	Code for France, Russia & S-Africa SWAP packages removed
Version 21	06.03.08	Code for cut-out cover front (for TIM) 9454222 removed
Version 20	23.07.07	Code for A-cover assy (9459088) removed (not available anymore)
Version 19	21.06.07	ITEM code for cut-out covers added
Version 18	29.05.07	Code for A-cover assy (0266412) removed (not available anymore). A-cover assy (9459088) with cut-out covers could be used instead.
Version 17	30.08.06	Code for cell capacitor changed (4700131 -> 4700135)
Version 16	16.05.06	Code for Turkey SWAP package (0050559) removed
Version 15	25.10.05	Code for Ukraine SWAP (0050565) removed
Version 14	13.06.05	Codes for cut-out covers (for Vodafone) added
Version 13	19.04.05	Code for cut-out covers for TIM added
Version 12	11.03.05	Code for RoHS compliant screw (6380223) added
Version 11	03.03.05	Codes for cut-out covers, silver A-cover and B-cover assemblies added. Czech SWAP code removed
Version 10	18.02.05	Code for FoHS compliant F100 (5119029) added
Version 9	01.02.05	Code for LCD (4850291 -> 4850813) changed.
Version 8	31.01.05	Code for power switch (with four solder terminals) added. Please see also SB-027
Version 7	17.12.04	Code for cut-out A-cover added
Version 6	20.09.04	Code for B-cover (TIM) added
Version 5	10.09.04	Code for CIF camera module changed (4858003 -> 4858021). Poland SWAP unit (0050560) removed
Version 4	23.03.04	Code for B-cover (Vodafone) added
Version 3	03.02.04	Code for display shield assembly (ITEM I004) added
Version 2	05.11.03	Code for battery connector removed
Version 1	20.10.03	Initial version

Note: Components in following list marked with **bold text** are new components, which have not been used in other older phone models.

☐ Level 1 ☒ Level 2 ☐ Level 3 ☐ Level 4

Version 21



		CMO / EMEA CUSTOMER CARE SALO		
--	--	-------------------------------	--	--



(LEVEL 2) SPARE PARTS LIST FOR				
TRANSCIVER RH-30 NOKIA 3200				
ITEM	CODE	DESCRIPTION	UNIT	NOTE
<b>I026</b>	<b>0266414</b>	<b>RIO B-COVER ASSY LIBAI SILVER</b>	<b>PC</b>	
G300	4700135	CELL CAPACITOR 0.01MAH 3V3	PC	
I003	4850813	LCD PM 130X130 COG COLOR	PC	
I012	4858021	CIF CAMERA MODULE	PC	See SB-022
F100	5119019	SM FUSE	PC	
F100	5119029	SM FUSE F 1.5A 32V 0603	PC	
S302	5200025	SM TACT SW SIDE TRAVEL	PC	See SB-027
S302	5200065	SM SW TACT SPST 12V SIDE KEY 3N	PC	See SB-027
I018	5400243	CONN DC-JACK 3.5MM 3POL SPR 90DEG	PC	
I024	5400263	ANTENNA POGO PIN L=8.7MM C2.12MM	PC	
I010	6290107	SCREW 1.8X7.0 FE T6+ DMD05791 BLK	PC	
I010	6380223	Screw 1.8x7.0 DIN8015 FH FeZn black	PC	
I019	6800057	VIB.MOTOR ASSY 1.3 VDC 11000 RPM	PC	
<b>I027</b>	<b>9430500</b>	<b>CUT-OUT COVER FRONT DMC07889</b>	<b>PC</b>	
<b>I028</b>	<b>9430502</b>	<b>CUT-OUT COVER BACK DMC07894</b>	<b>PC</b>	
<b>I022</b>	<b>9453197</b>	<b>POWERKEY DMD10923</b>	<b>PC</b>	
<b>I020</b>	<b>9453209</b>	<b>RELEASE KEY</b>	<b>PC</b>	
<b>I026</b>	<b>9453673</b>	<b>B-COVER ASSY (VODAFONE)</b>	<b>PC</b>	
<b>I026</b>	<b>9454143</b>	<b>B-COVER 040-001619 PRINTED TIM</b>	<b>PC</b>	
<b>I028</b>	<b>9454221</b>	<b>CUT-OUT COVER BACK TIM</b>	<b>PC</b>	
<b>I026</b>	<b>9459085</b>	<b>B-COVER ASSY DMC06661</b>	<b>PC</b>	
<b>I027</b>	<b>9470446</b>	<b>A-COVER CUT-OUT COVER DMD11186</b>	<b>PC</b>	
I013	9481013	CONN SHIELD CIF-J CLE9014-01E	PC	
-	<b>9498007</b>	<b>UI MODULE ASSY</b>	<b>PC</b>	
<b>I021</b>	<b>9511232</b>	<b>RELEASE SPRING</b>	<b>PC</b>	
<b>I004</b>	<b>9517307</b>	<b>DISPLAY SHIELD ASSY DMC06523</b>	<b>PC</b>	
<b>I002</b>	<b>9791009</b>	<b>KEYMAT ASSEMBLY ARABIC DMC06415</b>	<b>PC</b>	
<b>I002</b>	<b>9791011</b>	<b>KEYMAT ASSEMBLY RUSSIAN DMC06417</b>	<b>PC</b>	
<b>I002</b>	<b>9791012</b>	<b>KEYMAT ASSEMBLY GREEK DMC06418</b>	<b>PC</b>	
<b>I002</b>	<b>9791013</b>	<b>KEYMAT ASSEMBLY HEBREW DMC06419</b>	<b>PC</b>	
<b>I002</b>	<b>9791015</b>	<b>KEYMAT LATIN DMC06421</b>	<b>PC</b>	
<b>I027</b>	<b>9900233</b>	<b>A-COVER CUT-OUT COVER WATER SILK SILVER</b>	<b>PC</b>	
<b>I028</b>	<b>9900234</b>	<b>B-COVER CUT-OUT COVER WATER SILK SILVER</b>	<b>PC</b>	

**Note: When repairing RH-30 phones lead free rework must be used.**

## SWAP PACKAGES

CODE	DESCRIPTION
------	-------------

☐ Level 1 ☒ Level 2 ☐ Level 3 ☐ Level 4

Version 21

# NOKIA

0050558	RH-30 N3200 SWAP UNIT EUROPE & AFRICA
---------	---------------------------------------

All SWAP packages include SWAP engine without A-cover (I001), B-cover (I026) and keymat (I002)